

CUSTOM MADE I.D. SCARFING TOOLS



INNER Ø RANGE	PNEUMATIC SCARFING TOOL	Ring Holders	CUTTING RING Only top quality also specail coatings	EXTENDER	IMPEDER	FERRITE only top quality high permeability	TOW BAR	Mounting unit HOLDER OF TWO BAR
12 ~ 13	R.I.R.P.12-13	1	PSR0-R4,5~ R5,5	EX 12 - 13	I.R.I. 12 - 13	10,5x 5x200 (1 ferrite)	TOW 12-13	
13 ~ 15	R.I.R.P. 13 – 15	1	PSR0-R4,5~ R5,5	EX 13 - 15	I.R.I. 13 - 15	10,5x5x200 (1 ferrite)	TOW 13-15	H.R.I.R.13-15
14,5 ~ 18	R.I.R.P. 14,5 – 18	1	PSR0-R4,5~ 5,5	EX 14,5 - 18	I.R.I.14,5 - 18	12x6x200 (1 ferrite)	TOW 14,5-18	H.R.I.R.14,5-18
17 ~ 21	R.I.R.P.17 – 21	1	PSR0-R4,5~ 5,5	EX 17 - 21	I.R.I. 17- 21	14x7x200 (1 ferrite)	TOW 17-21	H.R.I.R.17-21
20 ~ 25	R.I.R.P.20 - 25	1	PSR0-R6,0 ~ 7	EX 20 - 25	I.R.I. 20 - 25	15x7x200 (1 ferrite)	TOW 20-25	H.R.I.R.20-25
24 ~ 32	R.I.R.P.24 – 32	1	PSR1-R8	EX 24 - 32	I.R.I. 24 - 32	18x9x200 (1 ferrite)	TOW 24-32	H.R.I.R.24-32
30 ~ 40	R.I.R.P.30 - 40	2	PSR1 PSR2	EX 30 - 40	I.R.I.30 - 40	22x11x200 (1 ferrite)	TOW 30-40	H.R.I.R.30-40
38 ~ 51	R.I.R.P.38 – 51	3	PSR1 PSR2 PSR3	EX 38 - 51	I.R.I.38 - 51	30x15x200 (1 ferrite)	TOW 38-51	H.R.I.R.38-51
48 ~ 62	R.I.R.P.48 - 62	3	PSR1 PSR2 PSR3	EX 48 - 62	I.R.I.48 – 62 I.R.I. 54- 62	38x19x200 (1 or 2 ferrites) 44x22x200 (1 or 2 ferrites)	TOW 48-62	H.R.I.R.48-62
58 ~ 80	R.I.R.P.58 – 80	2	PSR3 PSR4	EX 58 - 80	I.R.I.58 – 80 I.R.I. 65 - 80	46x23x200 (1 or 2 ferrites) 55x27x200 (1 or 2 ferrites)	TOW 58-80	H.R.I.R.58-80
75 ~ 100	R.I.R.P.75 - 100	3	PSR3 PSR4	EX 75 - 100	I.R.I.75 – 100 I.R.I. 85 - 100	60x30x200 (2 or 3 ferrites) (10) 16x200 (2 or 3 ferrites)	TOW 75-100	H.R.I.R.75-100
95 ~ 135	R.I.R.P.95 –135	3	PSR3 PSR4- PSR5	EX 95 - 135	I.R.I.95 – 135 I.R.I. 115 - 135	(12) 16x200 (2 or 3 ferrites) (11) 20x200 (2 or 3 ferrites)	TOW 95-135	H.R.I.R.95-135
120 ~160	R.I.R.P.120-160	3	PSR3 PSR4 PSR5	EX 120 - 160	I.R.I.120 – 160 I.R.I. 140 - 160	(11) 20x200 (2 or 3 ferrites) (12) 24x200 (2 or 3 ferrites)	TOW 120-160	H.R.I.R.120-160
140 ~ 190	R.I.R.P.140-190	3	PSR4 PSR5 PSR6		I.R.I.140 – 190 I.R.I. 160 - 190	(12) 24x200 (3 or 4 ferrites) (14) 24x200 (3 or 4 ferrites)	TOW 140-190	H.R.I.R.140-190
170 ~220	R.I.R.P.170-220	3	PSR4 PSR5 PSR6		I.R.I. 170 – 220 I.R.I. 180 - 220	(14) 24x200 (3 or 4 ferrites) (14) 26x200 (3 or 4 ferrites)	TOW 170-220	H.R.I.R.170-220